

This diagram shows how the panel metal flows into the undercut groove during installation.

A punch and back-up anvil are essential to proper self-clinching installation.