



**Bearings** | **Technical Data**

**More Info**

**Storage**

BEARING MEDIUM	STORAGE
Teflon-Bronze	Clean, dry area.
SAE-840 Bronze	Clean, dry area in nonabsorbent containers to prevent oil loss.
Delrin	Clean, dry area.
Needle-Roller	Clean, dry area, use rust preventative paper on crystals.

- [Mounting Options](#)
- [Coefficient of Friction](#)
- [Material Content & Structure](#)
- [Operating Temperature](#)
- [Shaft Requirements](#)
- [Maintenance](#)
- [Storage](#)
- [PV Values](#)
- [Wear/Life Calculation](#)